



APRIL 29, 2025

WS1.5 TWIN BOM CHANGE AND IMPROVEMENTS

THREADED INTERCONNECT FITTINGS NO LONGER INCLUDED

We have removed the interconnect 1.5" to QC threaded fittings from all WS1.5 Twin Control Valves. This will allow each customer to decide which fitting kits are needed between the tanks and as always, the fitting kit for inlet/outlet of the Control Valve that was purchased separately.

See the table below for all WS1.5 Twin fitting kits available (3 sets of fittings per valve).



ORDER NUMBER	DESCRIPTION	QTY PER CARTON
V4430-01	1.5" Composite Plastic NPT Straight Assembly	8 sets
V4430-02	1.5" Composite Plastic BSPT Straight Assembly	8 sets
V4430-11	1.5" Stainless Steel NPT Straight Assembly	8 sets
V4430-12	1.5" Stainless Steel BSPT Straight Assembly	8 sets
V4430-13	1.5/2" PVC Solvent Straight Assembly	8 sets
V4430-07	1.5" Composite Plastic NPT Elbow Assembly	8 sets
V4430-08	1.5" Composite Plastic BSPT Elbow Assembly	8 sets


There will be a new lower list price for each WS1.5 Twin Control Valve configurations to reflect the interconnect fitting kits being removed.

Please see your Sales Representative for pricing.

NEW DISC SPRING AND SOFTWARE UPDATE

We have made improvements to the disc spring and software.
There will be no part-number changes.

IMPROVEMENTS:



Updated software to handle the stronger disc spring.

CONTROLLER BOARD	SOFTWARE	
	CURRENT	NEW
CI	340.7	340.8
EI	621.2	621.3