



SEPTEMBER 10, 2026

PRODUCT UPDATE
DRIVE GEAR CHANGE

The drive gear for the WS2HF, WS3, 3" MAV, and 3" NHWB Drive Cap assemblies will no longer have 4 holes. This will be a rolling change as inventory is consumed.

The holes in the drive gear allowed access to the screws on the old Poppet Valve Drive Cap that has been discontinued since 2009.


CURRENT

FOUR HOLES IN GEAR



NEW

NO HOLES IN GEAR



If you have any questions, please contact us. • Thank You • Water Treatment Sales
4462 Duraform Lane • Windsor, WI 53598-9716
Phone (608) 846-3010 • Fax (800) 755-3010